

11.5.2 Service Limit States

C11.5.2

Revise the first sentence in paragraph one as follows:

Abutments, piers, and walls shall be investigated for excessive vertical and lateral displacement, bearing resistance, and overall stability, at the service limit state....

11.5.3 Strength Limit States

C11.5.3

Delete text in paragraph one as follows:

● ~~Bearing resistance failure~~

This page intentionally left blank.